## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

	Domestic / Import Vehicles			
CAMPAIGN No.	Gai-2574	DATE	December 15, 2017	
MANUFACTURE	Aston Martin Lagonda Limited			
DESCRIPTION OF DEFECT	incorrect transm transmission to overheat.  2. Transmission we connector is between system. It is pos	Transmission was found not to have sufficient support. The connector is between the pipe for the clutch fluid and the ASM system. It is possible that this connector can fail and cause loss of the clutch fluid. This would result in malfunction of the clutch		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
-	V8 Vantage V8 Vantage S V8 Vantage S Roadster	2011 - 2012	1 and 2 for 14 2 only 14
		TOTAL	28