VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4138	DATE	JAN-12-2018	
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Yoshiaki Nagao			
SUMMARY OF DEFECT	Due to the improper fixing torque for fixing the fuel tank and fuel measurement device, some rubber packings for sealing the fixing portion were deformed excessively. Therefore, due to its less sealability, when it is continued to use by keeping the condition, depending on the fuel carrying state, in the worse-case scenario, may result in the fuel leakage.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDN-S1091A	KIORITZ SPEED SPRAYER SSV1091 F SC	$2015 \sim 2017$	35
	KIORITZ SPEED SPRAYER SSV1091 F SC/L		52
	KIORITZ SPEED SPRAYER SSV1091 F SC/LT		1
	KIORITZ SPEED SPRAYER SSV1091 F SC/T		1
YDN-S1091B	KIORITZ SPEED SPRAYER SSV1091 F S	$2015 \sim 2017$	39
	KIORITZ SPEED SPRAYER SSV1091 F S/T		2
		TOTAL	130