

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4183	DATE	January 15,2018
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	On certain vehicles, the pipe nut to which the trailing arm is tightened has been welded on the rear right floor side member by inappropriate way, and as a result, the weld strength is insufficient. If use is continued in that state, there is a risk that the trailing arm may detach from the rear right floor side member and running stability may be compromised.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2017	2
		TOTAL	2