

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4174	DATE	Jan.17.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the front passenger airbag inflator of the subject vehicles, due to improper operation at the ignition booster filling process during suspension of the equipment, there is a possibility that the amount of filling could be small. In this condition, the airbag may not inflate properly during deployment.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE141	[COROLLA AXIO]	2006-2009	55
DBA-NZE144		2007-2008	2
DBA-ZRE142		2006-2009	15
DBA-NZE141G	[COROLLA FIELDER]	2006-2009	33
DBA-NZE144G		2007-2009	2
DBA-ZRE142G		2006-2008	16
DBA-ZRE144G		2006-2009	4
DBA-AZE154H	[BLADE]	2006-2008	11
DBA-AZE156H		2006-2009	18

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE151H	[AURIS]	2006-2008	19
DBA-NZE154H		2007	1
DBA-ZRE152H		2006-2008	7
DBA-ZRE154H		2007	3
DBA-NZE151N	[COROLLA RUMION]	2007-2009	12
DBA-ZRE152N			6
DBA-ZRE154N		2008	1
DBA-ZRR70G	[NOAH] [VOXY]	2007-2009	26
DBA-ZRR70W			36
DBA-ZRR75G			3
DBA-ZRR75W			10
DBA-GSE20	[IS250]	2005-2010	55
		2005-2011	58
DBA-GSE25		2006-2008	6
		2005-2011	10
DBA-GSE21	[IS350]	2005-2008	15
		2005-2011	16
DBA-USE20	[IS F]	2008-2011	12
		TOTAL	452