

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4154	DATE	Jan 18, 2018
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>In the rear wheel speed sensor which is the resin mold electric parts, of four-wheel drive vehicle, its resin may absorb moisture due to improper resin material use. Absorbed moisture may cause short circuit in the electric parts inside the sensor, resulting that the output signal from the sensor may be abnormal. If such condition occurred, the ABS warning light may be illuminated and the ABS function may be disabled, or the speedometer may not work.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HA25S	ALTO	2009~2010	10,500
DBA-HE22S	ALTO LAPIN	2008~2010	10,046
CBA-HE22S			759
DBA-MH23S	WAGON R	2008~2010	42,375
CBA-MH23S			10,659
DBA-MK21S	PALETTE	2009~2010	12,056
CBA-MK21S		2008~2010	20,715
DBA-ML21S	ROOX	2009~2010	7,182
CBA-ML21S			1,504

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HB25S	CAROL	2009~2010	1,697
DBA-MJ23S	AZ-WAGON	2008~2010	7,255
CBA-MJ23S			1,423
		TOTAL	126,171