

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4179	DATE	Jan. 18. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain light-duty trucks, because the fixing brackets of fuel piping and starter wiring are installed improperly, the routing position of fuel piping and starter wiring may become discrepant, causing the starter wiring and the peripheral part to interfere. Therefore, if it is continued to be used under the condition, the insulation of the wire may be damaged and short-circuited, resulting the engine to unable to start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZU600F	[HINO DUTRO]	2017	25
2KG-XZU640F		2017	6
2KG-XZU650F		2017	2
		TOTAL	33