

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4170	DATE	Jan, 19, 2018
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Brake master cylinder circlip may be deformed due to contact with the cylinder rod when brake pedal fully depressed for brake air release adjustment. It may push in the cylinder piston and close the hydraulic circuit, then leads to result in brake drag when oil heated up.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-SMF	「M108W」	2010~2013	779
		TOTAL	779