

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2585	Date	January 25, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Because the design dimension of the bulb holder for bulb fixing in rear combination lamp is inappropriate, contact failure might occur due to a vibration during driving. As a result, the warning lamp turn on then brake lamp/tail lamp might not light in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AUCHP	VW Golf Variant 1.4L	MY2014-2015	8,772
DBA-AUCJZ	VW Golf Variant 1.2L	MY2014-2015	6,909
ABA-AUCJXF	VW Golf R Variant 2.0L	MY2015	58
DBA-1TCZD	VW Golf Touran 1.4L	MY2016-2017	2,947
		Total	18,686