

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4167	DATE	January 25,2018
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to improper selection of resin for the sunroof glass outer frame, adhesion between the outer frame and the sunroof glass may be weakened depending on changes in temperature and humidity on vehicles with the sunroof glasses. If use is continued in that state, the sunroof glass may become detached from the outer frame. In the worst case, there is a risk that the sunroof glass may fall down due to vibration and wind pressure during driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-CW5W	「OUTLANDER」	2005～2006	1,895
		2007～2009	943
		2009	62
DBA-CW6W		2007～2009	242
		2009	19
CBA-CX4A	「GALANT」	2008～2009	54
DBA-CX4A		2008～2009	66
CBA-CY4A		2008～2009	68
DBA-CY4A		2007～2008	210
		2008～2009	69
CBA-CZ4A	「LANCER EVOLUTION」	2007～2009	384
		TOTAL	4,012

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
ROOF LID GLASS	5850A028	2009～2010	8
	5850A104	2009～2010	3