

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4192	DATE	January 25,2018
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	On the cylinder head of the engine, a steel ball is press-fitted into a machined oil passage hole as a plug. However, as a result of improper verification when the production equipment was changed, on certain cylinder heads, two steel balls were incorrectly press-fitted into the machined hole and oil passages are blocked. This may cause insufficient oil supply and the journals of the camshaft to seize.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA- B11W	「eK」	2018	1
DBA- B21W	「DAYZ」	2018	2
DBA- B21A	「DAYZ ROOX」	2018	1
		TOTAL	4