VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4185	DATE	Jan.31.2018	
MANUFACTURER	ТОУОТА			
DESCRIPTION OF DEFECT	In the air bag control system of the subject vehicles, due to improper manufacturing conditions of the IC chip embedded in the G sensor or pressure sensor, there is a possibility that the circuit in the IC chip could become open-circuit. If this were to occur, the air bag warning light will illuminate and the air bags will not be activated properly.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-AGH30W	[ALPHARD]	2015	19,919	#1
	[VELLFIRE]			
DBA-AGH35W			3,345	
DAA-AYH30W			10,513	
DBA-GGH30W			3,382	
DBA-GGH35W			1,425	
DAA-ZVW50	[PRIUS]	2015	11,045	#2
DAA-ZVW51			3,870	
DAA-ZVW55			3,411	

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-NCP175G	[SIENTA]	2015	782	#1
DAA-NHP170G			6,786	
DBA-NSP170G			4,012	
DBA-NSP172G			119	
DBA-ZRR80G	[NOAH] [VOXY]		1,010	
DBA-ZRR85G	[ESQUIRE]		388	
DAA-ZWR80G			2,663	
DBA-ZRR80W	[NOAH] [VOXY]		980	
DBA-ZRR85W			212	
DBE-NCP160V	[PROBOX] [SUCCEED]		2,098	
DBE-NCP165V			1,049	
DBE-NSP160V	[PROBOX]		947	
DBA-AGZ10	[NX200t]		2,804	
DBA-AGZ15			1,418	
DAA-AYZ10	[NX300h]		3,702	
DAA-AYZ15			2,158	
DBA-AGL20W	[RX200t]		57	#1,2
DBA-AGL25W			134	

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DAA-GYL20W	[RX450h]	2015	118	#1,2
DAA-GYL25W			186	
DBA-AGL20W	[RX200t]	2015-2016	185	#2
DBA-AGL25W			449	
DAA-GYL20W	[RX450h]		371	
DAA-GYL25W			1,672	
	ı	TOTAL		91,210