

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4186	DATE	February 1 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>Manufacturing of the steering knuckle for the steering system of the light-duty truck was not correct. As a result, some installation holes for the upper link have insufficient strength due to the defect of shape. Continued use could lead to increasing the diameter of the mounting hole due to running vibration, which may then generate rattle in the hole and impair running stability.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-NHR85AN TRG-NHR85A	[ELF]	2017	2
TPG-NJR85AN		2017	1
TRG-NLR85AR		2017	1
TFG-NMR82ZAN		2017	1
TRG-LHR85AN	[TITAN]	2017	2
TRG-LJR85A		2017	1
TRG-LKR85A		2017	1
TRG-LMR85AR		2017	1
		TOTAL	10