

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4175	DATE	Feb. 9, 2018
MANUFACTURER	SHO-SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	In the engine of the crop-dusting vehicles, because the engine control unit program is inappropriate, after turning off the ignition switch and stopping the engine, when the ignition switch is turned on after a specific time, the engine becomes unable to start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-J4	「3S-VE642」	2016-2016	50
EBT-J5	「3S-CE642H」	2016-2017	65
	「3S-FS642H」	2016-2016	35
EBT-J7	「3S-FSC600TLG」	2016-2017	40
	「3S-FSC1000TLG」	2016-2017	30
TOTAL			220