

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4203	DATE	Feb. 15. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain full air brakes of medium-duty trucks, some of the tightening bolts may be missing due to the improper tightening of the relay valve bracket. Therefore, if they are continued to be used under the condition, the bracket concerned may come off due to the driving vibration etc., resulting the air piping to be damaged and the air to leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FG2ABA	[HINO Ranger]	2017	6
		TOTAL	6