VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2592	DATE	Feb. 16, 2018	
MANUFACTURER	DUCATI MOTOR HOLDING SpA			
	(Japanese Importer : DUCATI JAPAN Ltd.)			
DESCRIPTION OF DEFECT	In the engine cooling system, since the durability of the radiator hose is			
	insufficient, cracks may occur inside the hose when traveling under			
	specific conditions. Therefore, if you continue to use it as it is, cracks will develop, cooling water will leak, in the worst case the engine may			
	overheat.			
The official Ducati dealer will rep			diator hose with the correct	
	one. This will be performed	ed free of charge		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-AA02	Multistrada1200/S Multistrada1200 Pikes Peak	2015-2017	343
EBL-AA02	Multistrada1200Enduro	2016	42
2BL-AA05	Multistrada950	2017	31
		TOTAL	416