

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4197	DATE	February 27 .2018
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	At transmission in agricultural tractor, turning front tire accelerating controller for turning performance improvement is inappropriately designed, which could generate ion migration in substrate and cause electric circuit short. Operating with that condition could eventually let shorted part abnormally generate heat into melted causing circuit disconnected. In the worst case, it may bring about loss of function in turning front tire accelerating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
A24	「RS-240」	1998～2001	1,753
A33A	「RS-270」	1998～2001	2,256
	「RS-300」	1998～2002	1,638
	「RS-330」	1997～2002	808
A16A	「AF-150」	1997～1999	910
	「AF-160」	1997～1999	1,446
A18A	「AF-170」	1997～1999	1,146
	「AF-180」	1997～1999	2,704
A16B	「AF114」	2000～2005	619
	「AF116」	2000～2005	2,902
A20	「AF118」	2000～2005	5,417
	「AF120」	2000～2005	7,626
A22A	「EF118」	2005～2011	195
	「EF120」	2005～2011	268
	「EF122」	2005～2011	160
TOTAL			29,848