VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4205	DATE	Feb. 27. 2018	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	On certain steering drag links of medium-duty trucks, the welding part may be different from the normal part due to the improper welding of the ball joint connecting part. Therefore, if the vehicle is used under the condition continuously, the welding of the ball joint connecting part may be peeled off, resulting the ball joint to come off and the vehicle unable to steer the wheel.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FC7JJAA	[HINO Ranger]	2017	4
TKG-FC7JJAG			
TKG-FC7JKAG		2017	1
SDG-FC9JCAA		2017	40
SDG-FC9JCAP			
TKG-FC9JCAA			
TKG-FC9JCAP			
TKG-FC9JEAA		2017	9
TKG-FC9JEAP			
SDG-FC9JGAP		2017	16
TKG-FC9JGAA			
TKG-FC9JGAP			
ТКС-FС9ЈНАА		2017	1
TKG-FC9JJAA		2017	28
TKG-FC9JJAG			
TKG-FC9JJAP			
SDG-FC9JKAP		2017	55
TKG-FC9JKAA			
TKG-FC9JKAG			
TKG-FC9JKAP			
TKG-FC9JLAP		2017	9
TKG-FC9JSAA		2017	1
SDG-FD7JEAA		2017	1
SDG-FD7JGAA		2017	1
TKG-FD7JKAG		2017	1
TKG-FD7JLAA		2017	31
TKG-FD7JLAG			
TPG-FD7JLAA			
TPG-FD7JLAG			
TKG-FD7JMAG		2017	1
TKG-FD7JPAA		2017	7
TKG-FD7JPAG			
TPG-FD7JPAA			
TPG-FD7JPAG			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FD9JGAA	[HINO Ranger]	2017	1
TKG-FD9JKAA		2017	7
TKG-FD9JLAA		2017	42
TKG-FD9JLAG			
TKG-FD9JPAA		2017	1
2KG-FC2ABA		2017	5
2KG-FD2ABA		2017	24
2KG-FD2ABG			
2PG-FD2ABA			
2PG-FD2ABG			
2KG-GX2ABA		2017	8
2PG-GX2ABA			
		TOTAL	294