

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2599	Date	February 28, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	<p>Because evaluation of durability for the ABS/ESC control unit is insufficient, crack may occur at the soldered part of the integrated circuit (IC) due to the heat in engine compartment.</p> <p>As the result, if the vehicle is continuously used as it is, the crack might progress then the power supply to the IC chip might be cut off, ABS/ ESC may not operate together with the warning lamp on.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	VW Scirocco 1.4L	MY2009	4
	VW Scirocco 2.0L		5
ABA-13CAV	VW Scirocco 1.4L		509
ABA-13CAW	VW Scirocco 2.0L		451
ABA-1FBUB	VW Eos 3.2L		26
ABA-1FBWA	VW Eos 2.0L		118
ABA-1FCAW	VW Eos 2.0L		34
ABA-1KAXX	VW Golf 2.0L		1,060
	VW Jetta 2.0L		455
	VW Golf Variant 2.0L		690
ABA-1KBLG	VW Golf 1.4L		1,781
ABA-1KBMY	VW Golf 1.4L		25
ABA-1KBUBF	VW Golf 3.2L		85
ABA-1KBYD	VW Golf 2.0L		908
ABA-1KCAV	VW Jetta 1.4L		MY2009
	VW Golf Variant 1.4L	MY2009-MY2010	2,952
	VW Golf 1.4L	MY2009	2,024
ABA-1KCAW	VW Golf Variant 2.0L		160
ABA-1KCAX	VW Golf 1.4L	MY2009-MY2010	5,575
	VW Golf Variant 1.4L		1,973
ABA-1KCCZ	VW Golf Variant 2.0L	MY2010	15
		Total	19,447