

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4215	DATE	Mar 8, 2018
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>On mild-hybrid models and hybrid models, due to lack of strength of the water pump belt driving ISG (Integrated Starter Generator) and the water pump, the belt may break during usage.</p> <p>If the belt is broken, ISG and the water pump became inoperative, the charging light comes on due to shortage of generated voltage and the coolant temperature warning light comes on due to rise of coolant temperature. In the worst scenario, engine may stall and may not be able to re-start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-MA36S	SOLIO	2015~2017	63,784
DAA-MA46S			3,160
DAA-FF21S	IGNIS	2016~2017	29,521
DAA-ZC53S	SWIFT		4,773
DAA-ZD53S			1,510
DAA-MB36S	DELICA D:2	2015~2017	9,115
DAA-MB46S		2017	862
		TOTAL	112,725