

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4208	DATE	Mar.9 2018
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For the headlight unit of the wheel crane, found that the fixing bolts of the light and the nuts of adjusting optical axis might not be tightened correctly. Therefore, it might cause to slack of them due to vibration while driving, then, eventually optical axis could fluctuate or it might not be able to re-adjust.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS - KRC019	KRM - 20H	2018	30	
		TOTAL	30	