

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	4212	DATE	March 12 , 2018
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	As some of the bumper stay mounting parts on the main frame of the rear folding tailgate lifter have been found to be insufficient in strength, cracks may occur due to vibration etc. during travel. Continued use as is, poses a risk for cracking to progress further, causing the bumper stay to deviate from its position, and in the worst case, be dragged behind the bumper body. Check for cracks on all vehicles. For those without cracks, add reinforcing material to the main frame and the bumper stay installation area. For those with cracks, repair the cracks and weld with additional reinforcing material.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ISUZU	PJ-CYJ77W6A	GIGA	2016	1
HINO	TKG-FD7JLAG	HINO RANGER	2016	1
	LDG-FG8JPAA	HINO RANGER	2016	1
	QKG-FE7JUAG	HINO RANGER	2017	1
	QKG-FJ7JNAA	HINO RANGER	2017	5
	QPG-FQ1EWEG	HINO PROFIA	2016-2017	7
	QKG-FQ1EWEJ	HINO PROFIA	2017	1
	QPG-FR1EXEG	HINO PROFIA	2017	2
MITSUBISHI	QPG-FS64VZ	FUSO SUPER GREAT	2016-2017	8
	2PG-FS74HZ	FUSO SUPER GREAT	2017	5
	QPG-FY64VY	FUSO SUPER GREAT	2016	1
UD TRUCKS	QKG-PK39CH	CONDOR	2017	1
	QPG-CG5ZA	QUON	2016	1
	2PG-CD5CA	QUON	2017	1
			TOTAL	36