

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4213	DATE	March 12 , 2018
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	For larger truck models, as some rear combination lamps have been installed in reverse (left/ right), water drainage has not been adequate leading to the risk of the lamps not working. There is also a danger that the lighting provided by the rear lamps will differ from the original design and will therefore not comply with safety standards. Check the installation of the rear combination lamps in all vehicles, and reinstall in the correct position if required.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UD TRUCKS	2PG-CD5BA	QUON	2017	1
	2PG-CD5BL	QUON	2017	1
	2PG-CD5CA	QUON	2017	2
	2PG-CD5CL	QUON	2017	1
	2PG-CW5BL	QUON	2017	2
	2PG-CW5CA	QUON	2017	1
	2PG-CW5CL	QUON	2017	2
			TOTAL	10