

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4228	DATE	Mar.28.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ANH20W	[ALPHARD] [VELLFIRE]	2013-2014	80,452
DBA-ANH25W			14,672
DAA-ATH20W			20,686
DBA-GGH20W			7,799
DBA-GGH25W			3,302
DBA-ZRR70G	[NOAH] [VOXY]	2013	28,703
DBA-ZRR70W			30,769
DBA-ZRR75G			5,096
DBA-ZRR75W			7,283
DBE-NCP50V	[PROBOX]	2013	10,529
QFE-NCP52V			44

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBE-NCP51V	[PROBOX] [SUCCEED]	2013	20,529
DBE-NCP55V			10,566
DBA-NCP58G			3,028
DBA-NCP59G			1,235
DBA-NZE151N	[COROLLA RUMION]	2013	2,922
DBA-ZRE152N			1,202
DBA-ZRE154N			656
		TOTAL	249,473