

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2624	DATE	March 29 <sup>th</sup> , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The fuel tank may have a welding fault on the lid of the mounting hole for the suction jet pump. Due to driving vibration etc., this may lead to the formation of cracks at the weld seam, where the fuel may leak from.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3A20	BMW 328i	2011 - 2013	2,249
DBA-3B20	BMW 320i	2012 - 2013	12,708
		TOTAL	14,957