VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2635	DATE	March 30 2018	
MANUFACTURE	FCA US LLC			
	(Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)			
DESCRIPTION OF DEFECT	The driver airbag inflator housing on the cars concerned may rupture, due to excessive internal pressure, during normal airbag deployment events. This condition is more likely to occur if the vehicle has been exposed to high levels of absolute humidity for extended periods of time. An inflator rupture, during airbag deployment events, could result in metal fragments striking and potentially seriously injuring the vehicle occupant(s).			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-LX35	L300C7	2009–2010	205
ABA-LX57	[300C]	2009–2010	21
Unknown	Г300C SRT8J	2009	1
		TOTAL	227