

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4225	DATE	Mar.30 2018
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>① For the exhaust pipes of the wheel cranes, we found it might have insufficient seals since we fitted the wrong clamp on the pipe joint which is connected to the front of the NOx after-treatment device, accordingly, it could have urea water and exhaust gas leaked from the joint.</p> <p>② For the exhaust pipes of the wheel cranes, it might have water drained from the pipe which is connected to the rear of the NOx after-treatment device and stain the machine body since it has a hole to drain water at the incorrect position.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS - KRC017	KR - 25H	2016~2017	96 台	①②
		2017~2018	109 台	①
		2017	1 台	②
		TOTAL	206	