VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4230	DATE	March 30 , 2018
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Exhaust pipe (Urea aqueous solution mixing tube) of the diesel engine may lack corrosion resistance because of improper welding process. Accordingly, welding position may become eroded by corrosion component and crack. If the diesel engine is used as it is, its exhaust pipe may crack by engine vibration, and exhaust gas leaks in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-GD032	「GD675-6」	2015 - 2017	144
YDR-WA136	「WA270-8」	2016-2017	33
YDR-WA135	「WA320-8」	2017-2017	11
YDS-WA130	「WA380-8」	2016-2017	76
		TOTAL	264