

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4231	DATE	2018.3.30
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO.,LTD.		
DESCRIPTION OF DEFECT	The rear axle of shovel loader may get damaged if it is used continuously since there is a possibility that the diff case may get cracked depend on the factors such as work load due to the insufficient strength of diff case inside the rear axle. When the diff case is broken, abnormal noise may occur and the traveling might malfunction in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
L2DA	「V2-3」	2003 to 2015	69
	「V2-3B」	2015 to 2017	296
WA117	「WA20-6」	2010 to 2017	378
TOTAL			743