VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4233	DATE	April 3 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The production process of the exhaust gas recirculation (EGR) pipes for the engines of heavy-duty tractors is not proper. As a result, the strength of some of the welded flange sections of the EGR pipes is insufficient. Because of this, there is a danger that the vibration of the engine may cause cracks in the welded sections of these pipe flanges, and the cracks may cause exhaust gas leakage.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QKG-EXD52BD	[GIGA]	2017	28
QKG-EXD52BE		2017	8
QKG-EXD52BG		2017	1
QKG-EXY52BJ		2017	1
QDG-EXZ52BJ		2017	9
		TOTAL	47