

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2629	DATE	April 4,2018
MANUFACTURER	Mitsubishi Motors(Thailand)Co., Ltd.		
DESCRIPTION OF DEFECT	In the inflator for the driver side airbag, the propellant may be deteriorated by the repetitive changes of temperature and humidity due to improper performance in moisture absorption prevention of the propellant. As a result, the inflator body may rupture at the time of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-KB9T	「TRITON」	2006~2010	1,400
		TOTAL	1,400