

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4221	DATE	April 5 , 2018
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Rainwater, etc. may enter a shovel loader through clearances because of improper external structure around the starting motor. As a result, rainwater, etc. may soak into the case of starting motor magnet along the wiring and piping and can rust the inside, and the engine cannot start in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-WA120	「WA470-7」	2012 - 2016	55
YDS-WA129	「WA470-8」	2017	16
TOTAL			71