

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | 4 2 4 3 | DATE | April.05.2018 |
| MANUFACTURER | N I S S A N | | |
| DESCRIPTION OF DEFECT | <p>Because tightening condition of a balancer sprocket bolt was inappropriate in balancer sprocket assembly process at the engine assembly line, there were some engines installed the bolt as temporary tightening condition. Therefore if the vehicle continues to be driven in this condition, the bolt loosens during a run, in an extreme case, the engine might be broken.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|----------|-----------------|---------------------|--------------------|
| DBA-TB17 | SYLPHY | 2018 | 7 |
| | | TOTAL | 7 |