

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2636	DATE	April 06, 2018
MANUFACTURE	Aston Martin Lagonda Limited		
DESCRIPTION OF DEFECT	In the affected models, it is possible that the seat rail can compress the battery supply cable due to inappropriate wiring fixing design. When the damage to the insulation of the cable occurs, it is possible that the excessive electricity conduction in the earth wire inside of seat frame makes a short circuit.it might be happen when not conducted initial setup on seat control unit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	DBS Coupe DBS Volante	2007-2012	77
	DB9 Coupe DB9 Volante	2005-2015	544
	Virage Coupe Virage Volante	2010-2012	40
ABA-AM301	Vanquish Coupe	2015-2015	3
		TOTAL	664