

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4238	DATE	Apr.12,2018
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>①On some wheel crane exhaust pipes, there are cases where the weld joints are not of adequate strength due to improper welding processes leading to the joints cracking from the engine's vibrations. Therefore, with continued use in this condition, the crack progresses, the weld joint breaks and the exhaust gas leaks, and in the worst case, it may not satisfy the reference values of noise and exhaust gas.</p> <p>②On some wheel crane exhaust pipes, there are cases where stress is generated in the flange due to improper fixing method leading to the flange cracking from the engine's vibrations. Therefore, with continued use in this condition, the crack progresses, the flange breaks and the exhaust gas leaks, and in the worst case, it may not satisfy the reference values of noise and exhaust gas.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-T014	TADANO 「GR-160N-4」	2017-2018	164
YDS-EW08	KOBELCO 「RK160-8」	2017-2018	6
		TOTAL	170