

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2637	Date	April 13, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	<p>On the passenger airbag module, the end cap and the igniter carrier are not properly welded due to improper production of the inflator.</p> <p>As a result, cracks may occur in the welded portion due to the pressure of the gas at deployment of the airbag then the deploying pressure of the airbag decreases due to gas leakage at the cracked portion.</p> <p>In the worst case, the occupants may get injured severely.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-7NCZD	Sharan1.4L	MY2017	10
		Total	10