

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4245	DATE	April 27 .2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	The structure mounted at exhaust pipe stay which fixed at engine is inappropriately designed, mounting hole of exhaust pipe stay was assembled in a state that they do not match the hole with bracket hole of exhaust pipe. Vibration of the engine causes the exhaust pipe to swing and the stay and bracket of exhaust pipe receive excessive stress and damage. In the worst case, exhaust pipe may crack and exhaust gas may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「YT463」	2015~2017	400
	「YT470」	2015~2017	750
TOTAL			1,150