## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2655	DATE	May 10 <sup>th</sup> , 2018	
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	① Due to an inappropriate production of fuel delivery unit, the mechanism might not work, which adjusts the different of fuel level on right and left side of the fuel tank. Thus, even there is some fuel left in the tank, the fuel delivery unit might not transfer fuel to the engine, and in worst case, this could lead to engine stalling.			
	the rear spoiler mid occur during drivin	Due to an inappropriate production control, the bolts for mounting the rear spoiler might be missing. Thus, whistling noise might occur during driving and, in worst case, the rear spoiler might detach at high speed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-TX20	BMW X3 xDrive20d	2017 - 2018	1,215
		TOTAL	1,215