

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2656	DATE	May, 15 <sup>th</sup> , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing, the transistor installed in the control units for the LED headlight have higher internal resistance. Thus, if the LED headlight is on when starting the engine etc. where the load of the transistor is high, the transistor might be damaged and the LED headlight does not turn on. This will not comply with the Japanese safety regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LN15	MINI Cooper Clubman	2017	332
DBA-LN20	MINI Cooper S Clubman	2017	133
LDA-LR20	MINI Cooper D Clubman	2017	230
	MINI Cooper SD Clubman	2017	133
DBA-LVJCW	MINI JCW Clubman	2017	58
DBA-XS12	MINI One 5 Door	2017	14
DBA-XS15	MINI Cooper 5Door	2017	81
DBA-XS20	MINI Cooper S 5Door	2017	98
LDA-XT15	MINI Cooper D 5Door	2017	106
LDA-XT20	MINI Cooper SD 5Door	2017	98
DBA-XM12	MINI One	2017	3
DBA-XM15	MINI Cooper	2017	78
DBA-XM20	MINI Cooper S	2017	122
LDA-XN15	MINI Cooper D	2017	98
LDA-XN20	MINI Cooper SD	2017	56
DBA-XMJCW	MINI JCW	2017	125
DBA-WG15	MINI Cooper Convertible	2017	4
DBA-WG20	MINI Cooper S Convertible	2017	4
DBA-WHJCW	MINI JCW Convertible	2017	4
		TOTAL	1,777