

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4264	DATE	May.23.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the air bag control system of the subject vehicles, due to improper manufacturing condition of the IC chip embedded in the G sensor, there is a possibility that the circuit in the IC chip could become open-circuit. If this were to occur, the air bag warning light will illuminate and the air bags will not be activated properly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-NCP175G	[SIENTA]	2015	42	
DAA-NHP170G			365	
DBA-NSP170G			225	
DBA-NSP172G			7	
DBA-AGL20W	[RX200t]		41	
DBA-AGL25W			80	
DAA-GYL20W	[RX450h]		116	
DAA-GYL25W			363	
		TOTAL	1,239	