

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4276	DATE	June 7, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the breather hose to release air inside fuel tank, due to improper hose material, some of breather hoses may deteriorate and crack under radiated heat influence of the exhaust system. As a result, in continuous use, the crack may develop leading to fuel leak. In the worst case, a fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2M	Mazda 「Bongo」	2012	129
ABF-SKP2V		2012	293
ABF-SKP2MN	NISSAN 「VANETTE」	2012	166
ABF-SKP2VN		2012	1
		Total	589