

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2675	Date	14,06, 2018
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper prevention for humidity control of Driver airbag inflator, propellant inside may suffer material wear under high humidity environment with temperature changing. As a result, container of the inflator may rupture when airbag deploy.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-9NBKY	Polo 1.4	MY2007	786
GH-9NBTS	Polo 1.6	MY2007	149
		Total	935