

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4273	DATE	Jun.14, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate material of an electric wire harness connected to a fuel pump, contact state of connector terminal may deteriorate during vehicle usage, and may end up with conduction failure. In that case, the fuel pump may malfunction, potentially causing an engine to stall and/or fail engine start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-BL5 ABA-BL5 CBA-BL5	「LEGACY」	2004~2009	48,840
DBA-BL9		2007~2009	1,443
TA-BP5 ABA-BP5 CBA-BP5		2004~2009	109,175
UA-BP9 CBA-BP9 DBA-BP9		2004~2009	35,073
CBA-BPH		2008~2009	1,502
DBA-GE2	「IMPREZA」	2008~2009	1,435
DBA-GE3		2008~2009	756
DBA-GH2		2007~2009	24,826
DBA-GH3		2007~2009	9,658
		TOTAL	232,708