

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4279	DATE	June 14, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the diesel engine, due to inappropriate program of engine control program, abnormality of small engine rotation at engine shut-off is detected, and the power supply to the engine control computer may not stop. Therefore, start stop unit determines there is a short circuit of starter circuit and when the push button start is pushed, power position is not changed to ON position, engine may not start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-KG2P	Mazda「CX-8」	2017-2018	16,008
3DA-KF2P	Mazda「CX-5」	2018	7,200
		Total	23,208