

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | 4268 | DATE | Jun. 15. 2018 |
| MANUFACTURER | SHINMAYWA INDUSTRIES LTD. | | |
| DESCRIPTION OF DEFECT | Due to improperly designed circuit of hazard lamp blinking control unit interlocking with PTO of refuse compactors, cornering lamps can start blinking when operating headlight or turning indicators while hazard lamp is blinking interlocking with PTO. Therefore, those vehicles is likely to fail to conform to article 33-2 of safety regulations for road vehicles. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|--|-----------------|---------------------|-------------------|
| TKG-NKR85N TPG-NKR85N TPG-NKR85AN TSG-NKR85KAN | 「ELF」 | 2014~2017 | 46 |
| SKG-NKR85YN TKG-NKR85YN | | 2014~2017 | 47 |
| TPG-NKS85AN TKG-NKS85AN | | 2015~2017 | 10 |
| TFG-NMR82ZN | | 2016 | 3 |
| TFG-NMR82ZAN | | 2016~2017 | 4 |
| TKG-NMR85N TKG-NMR85AN TPG-NMR85N TPG-NMR85AN TSG-NMR85N TSG-NMR85KAN | | 2014~2017 | 347 |
| TKG-NMS85AN | | 2016~2017 | 2 |
| TFG-NPR82ZN | | 2015 | 1 |
| TPG-NPR85AN | | 2015~2017 | 12 |
| TKG-NPR85YN SKG-NPR85YN TPG-NPR85YN | | 2014~2017 | 257 |
| TPG-NPS85AN | | 2016 | 2 |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---|-----------------|---------------------|-------------------|
| PKG-FRR90S2 TKG-FRR90S2 TKG-FRR90S1 | 「FORWARD」 | 2014~2018 | 144 |
| TKG-FRS90S2 | | 2016 | 1 |
| SKG-FSR90S2 SPG-FSR90S2 | | 2014~2017 | 64 |
| SPG-FSS90S2 SKG-FSS90S2 | | 2015~2017 | 7 |
| LPG-FTR90S2 LKG-FTR90S2 | | 2015~2017 | 19 |
| TPG-LKR85AN | | 「TITAN」 | 2016~2017 |
| TKG-LKR85YN | 2016 | | 1 |
| TPG-LMR85N TPG-LMR85AN | 2016~2017 | | 5 |
| TPG-LPR85AN | 2017 | | 1 |
| TKG-LPR85YN | 2017 | | 1 |
| TKG-BMR85N | 「CONDOR」 | | 2015 |
| TKG-BPR85AN | | 2015 | 1 |
| | | TOTAL | 979 |