

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4288	DATE	June 22, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain driver airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to high absolute humidity, high temperature and high temperature cycling. Therefore, during the airbag deployment, the container of inflator may be broken, components may be scattered, causing passengers to be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KR-SYF4T	Mazda 「TITAN」	2006	2
KK-WH35D		2004	1
KK-WH3HD		2004	2
KK-WH63G		2004	1
KK-WH63H		2004	1
KK-WH65D		2004	1
KK-WH65T		2004	2
KK-WH69H		2004	1
KK-WH6HD		2004	2
KK-WHF3G		2004	1
KK-WHF5D		2004	1
KK-WHF5T		2004	3
KK-WHS5T		2004	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2T	Mazda 「BONGO」	2012 – 2014	3
ABF-SKP2V		2014	1
		Total	25