

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2679	DATE	June.28, 2018
MANUFACTURER	Wuyang-Honda Motors (Guangzohou) Co., Ltd.		
DESCRIPTION OF DEFECT	<p>Because the winker switch harness is routed inappropriately and the clip band securing the harness to the vehicle body is at an inappropriate location, the harness may be bent at the clip band location when the steering wheel is turned while driving. If the vehicle continues in service in such a condition, the harness would be bent repeatedly, and as a consequence a break could occur in the harness, causing malfunction of headlights, turn signal indicators, brake lights and/or horn or the starter switch failure to start the engine.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AA03	「BENLY」 「BENLY PRO」	2011～2015	18,477
JBH-AA05		2015～2017	6,706
EBJ-JA09	「BENLY 110」 「BENLY 110PRO」	2011～2017	11,272
		TOTAL	36,455