

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4291	DATE	June 28, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to temperature cycling under humid condition. Therefore, during the airbag deployment, the container of inflator may be broken, components may be scattered, causing passengers to be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-ER3P	Mazda 「CX-7」	2006-2008	9
DBA-GH5FS	Mazda 「ATENZA」	2007	2
DBA-GH5FP		2007	1
DBA-GH5FW		2007	1
DBA-GHEFP		2009	1
DBA-GHEFW		2007-2009	4
		TOTAL	