

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4297	DATE	July 12, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the gas charging type of liftgate stay damper, due to the inappropriate coating of outer tube at the end-cap, the stay damper may corrode by salt at the salt damage region. Therefore, continued to use under the condition, the corrosion advances and outer tube swells and the end cap may crack. In the worst case, when opening the lift gate, the outer tube may break off, resulting in injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BL3FW	Mazda 「Axela」	2009-2012	17
DBA-BL5FW		2009-2013	101
DBA-BLEAW		2010-2011	5
DBA-BLEFW		2009-2011	62
DBA-BLFFW		2011-2013	55
		Total	240