

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4298	DATE	July 12, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the camera which confirms the situation in front of and on the left side of the vehicle, due to inappropriate coating of the lens surface, the acid included in the cleaning agent, rain, and so on, may corrode the coating, and continuous use may make the lens itself corroded and clouded, the view of the side camera may not be clear gradually. In the worst case, the driver may not confirm the situation in front of and the left side of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KE2AW	Mazda 「CX-5」	2012-2013	8
LDA-KE2FW		2012-2014	6
DBA-KE5AW		2013	1
DBA-KE5FW		2013	1
DBA-KEEFW		2012	4
		Total	