

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4300	DATE	20-July-2018
MANUFACTURE	KCM Corporation		
DESCRIPTION OF DEFECT	Due to the structural problem of the motor brush of the fuel pump on the shovel loader (wheel excavator), the brush can be abnormally worn away, and can cause a contact defect. This can cause a malfunction of the fuel pump, and in the worst case, the engine may stop and cannot be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
WDP-H79	「ZW100-5B」	2014-2017	2519	
WDP-H78	「ZW120-5B」	2014-2017	403	
YDP-H88	「ZW100-6」	2017-2018	87	
YDP-H87	「ZW120-6」	2018	1	
WDP-50D1	「50Z7」	2014-2016	224	
WDP-60D1	「60Z7」	2014-2016	67	
TOTAL			3301	